TROUBLESHOOTING

Battery undercharging (voltage not raised to regulated voltage)