



Carburetor Adjustment & Tuning Tips



- (4) air vent hoses
- (5) overflow hose

Idle Speed Adjustment

1. If the engine is cold, start it and warm it up 3 minutes and then shut it off.
2. Connect a tachometer to the engine.
3. Shift into neutral. Start the engine.
4. Keep the motorcycle in an upright position.
5. Adjust idle speed with the throttle stop screw (1).

Idle speed:
1,700 ± 100 rpm



- (1) throttle stop screw