
Gauges, Indicators & Displays

Multi-function Display

The multi-function display (1) includes the following functions: odometer tripmeter coolant temperature meter

The tripmeter will reset if the battery is disconnected.



(1) multi-function display

Instruments & Controls 19

