



Gauges, Indicators & Displays



- (1) mode switch
- (2) odometer
- (3) tripmeter A
- (4) tripmeter B
- (5) digital clock

To reset the tripmeter, push and hold the reset switch (6) for more than 2 seconds when the display is in the “TRIP A” or “TRIP B.”



- (6) reset switch