



Competition Inspection

No	Item	Inspect For:	Action	Refer to Page:
14	swingarm bearings	smooth operation	replace	89
15	rear suspension linkage bushings	wear	replace	89
16	brake pads	wear beyond service limit	replace	110
17	drive chain: max. length/pin	67.2 in (1,707 mm) / 108 pins	replace	125
18	sprockets	wear and secure installation	replace or tighten	126
19	seat	security	tighten	60
20	headlight	proper beam aim	adjust	130
21	tripmeter	proper operation	replace	19
22	control cables	smooth operation, kinks and correct routing	lubricate or replace	—
23	engine mounting bolts	tightness	tighten	—

