Competition Inspection

No	Item	Inspect For:	Action	Refer to
				Page:
11	swingarm bearings	smooth operation	replace	80
12	rear suspension linkage	smooth operation and secure installation	replace	80
	bearings		or tighten	
13	brake pads	wear beyond service limit	replace	85
14	drive chain:	25.1 in (638 mm) / 41 pins	replace	100
	max. length/pin			
15	sprockets	wear and secure installation	replace or	101
			tighten	
16	seat	security	tighten	_
17	control cables	smooth operation, kinks and correct	lubricate or	_
		routing	replace	
18	engine mounting bolts	tightness	tighten	=