


Replacing the Honda Smart Card Key Battery

When the Honda smart card key indicator (1) flashes 5 times or the operating range becomes unstable, replace the battery.

Battery type: CR2032



(1) Honda smart card key indicator