



ELECTRICAL SYSTEM

DTC 33-2 (EEPROM)

1. EEPROM System Inspection

- Check the EEPROM with MCS.
- Is the DTC 33-2 is indicated?

Yes ▼

- Replace the ECM with a new one. →4-19, and re-check.

No
▶

- Intermittent failure
- Loose or poor contact at the connector